Six Terminal Relay

1) Incoming Power
   a) One hot to L1
   b) One hot to L2
   **c)** Ground to ground

2) Limit Switch
   a) cut ground off,
Don't use!
   b) Cut connetor from pigtail
   c) Connect one limit switch lead to one of the pigtail leads
   d) Connect one limit switch lead to one of the pigtail leads

*In Case Of No Pigtail
   a) Cut wire from terminal #0 to the mirco switch
   b) Connect limit switch leads as if it was the pig tail